
كب ماللداز حمن أزحيهم



CLARIFICATION 2

و سرمنظ مر قرق و شرمن مرو سرو د که قرف مرف مرف م

م، موجر ومنشو شر2

ىتۇنلۇغ بر No:	TES/2020/W-040		
وَحَجَّةُ Project:	Design, Survey and Construction of Ha.Uligamu		
قرس مورد Issued Date	April 4, 2020		
<u>ب مؤرّد</u> برغرقر No. of Pages: -01	ی.د. بر Boq: -00	ن توزير Drawings: -00	

وي در رو ور ورو ورو المروم ورو المروم ورو المروم ورو المروم ورو المروم والمروم و

#	Query	Response
1	It is mentioned in the BOQ that scouring apron protection has to be done from the existing quay wall too. In such a case, can you provide the depth and type of the exisiting quay wall?	Depth is -3m MSL and the quay wall is L - Block
2	Quantity of harbour lights provided in the BOQ seems higher while calculating as per the spacing. Kindly conform the quantity. If the quantity is correct, please provide the location where the additional quantity needs to be installed.	additional quantity will be installed in the breakwater
3	kindly identify the power source of location for the harbour lights	It will be nearest Distribution Board. The distance to nearest DP will be with in a 100m Radius from the harbour
4	the provisional sum for the dismantling of existing breakwater and quay wall is not specified in the BOQ, can we include the costing details in additions. Kindly clarify Extension of time	revised boq will have the component added
5		Time extensions will be considered accordingly. We will review the requests and if necessary will give EQT or remainder the second seco
		+ () + + + + + + + + + + + + + + + + +