



AMENDMENT 3

މަނުކުލާ 3

ނަންބަރު No:	TES/2015/W-114		
މަނުކުލާ Project:	Construction of Lh. Naifaruu Atoll Hospital Extension		
މުދާ Issued Date	Monday, August 24, 2015		
ފޮޓޯ ކޮޕީ No. of Pages: -04	ބޯޖު Boq: -	ޔަގުޔުމްތަކުގެ ސެޓްތައް Drawings: -	މިލެކުޔުކަން ބޭނުންކުރާ ފަންނުތައް Other Documents: -

Please include this amendment when submitting the bid. ސަލާމަތުގެ ނިމިގެންދާ ކޮންމެ ފަހަރެއްގައި ޕްލީގެ ބެނިފައިވާ ދާއިރާތަކުން ޖަނުވާލާލެވޭ ޕްލީއަށް ޔަގުޔުމްތަކުގެ ސެޓްތައް ލިބިދޭނެ ގޮތް ނަންބަރު 3 ގެ ފޮޓޯ ކޮޕީއާއެކު ލިބިދޭނެ ގޮތް ބަނޑުވާނެއެވެ.

- Answers to clarifications is provided with this amendment.
- Bid Submission date and time is revised as follows.

ITB Clause Number	ITB Reference
19.1	<p>For bid submission purposes only, the Employer's address is:</p> <p>Mr. AHMED MUJUTHABA, Director General Tender Evaluation Section Ministry of Finance and Treasury Ameenee Magu Male', 20379 Republic of Maldives Tel: (960) 3349203, (960) 3349106 Fax: (960) 3320706, (960) 3324432 E-Mail: tender@finance.gov.mv</p> <p>The deadline for bid submission is: Date: Monday, September 07, 2015 Time: 1100 Hours Maldives Time</p>

ނަންބަރު
Name: Nimal Yoonus

ސަފްތާ
Signature:





MINISTRY OF HEALTH
ADMIN DIVISION

Amendment-2

Project: Construction of 5 Story Hospital Building at Lh.Naifaru

#	Query	Answer
1	CCTV Monitoring and recording system location / specifications is not mentioned please provide the details	CCTV Monitoring and recording system's Location is Second floor of adjoining building, the floor plan of this building has been provided as well as the specification has also been provided in the previous amendment
2	Server Room details not mentioned. Please provide the details	Server Room's Location is Second floor of adjoining building, the floor plan of this building has been provided in the previous amendment
3	Please provide the existing PABX location	Lay the cables up to adjoining building's second floor.
4	Please provide the lift bed elevator capacity details /specification	Details/specification has been provided with the previous amendment
5	Please provide the details / specification of the dumbwaiter	Details/specification has been provided with the previous amendment
6	Fire water tank location not mentioned in the drawing. Please clarify	It is a dry riser system therefore no fire pump or fire water tank is required.
7	As per the drawing fire pump location is mentioned outside the boundary wall. It is supposed to be breaching inlet for dry riser system. Therefore kindly provide the fire pump location.	It is a breaching inlet for dry riser system therefore no fire pump or fire water tank is required.





MINISTRY OF HEALTH
ADMIN DIVISION

Amendment-2

Project: Construction of 5 Story Hospital Building at Lh.Naifaru

8	Confirm whether bead panel required or not	Bed head panel is required for the locations in the drawing. The panel should include oxygen inlet, vacuum inlet, 2 electric sockets (13 Amps.)
9	Piped and tested oxygen delivery system from a central tank location mentioned in the BOQ, please provide us the drawings/details for oxygen system and vacuum plant system	All pipes shall be laid from Ground floor (MEDICAL RECORDS ROOM) to required designations. Shop Drawings shall be submitted by the contractor. Only complete piping works are required.
10	Please indicate the vacuum plants locations in the drawing	No Vacuum plant is required. Only Complete piping works is required.
11	Nurse calling system is not included. Please clarify whether required or not	Not required.
12	Scrub sink is shown in the drawing but not mentioned in the BOQ. If need to include please provide details.	No Scrub is required. Only fresh water inlet and waste water outlet is required. Scrub sink will be provided by client, contractor has to connect / install the scrub sink
13	Bed pan cleaning location not mentioned in the drawing. If required please indicate location with necessary requirement	Not required.
14	Timber Door will be varnish or paint finish	Paint finish





MINISTRY OF HEALTH
ADMIN DIVISION

Amendment-2

Project: Construction of 5 Story Hospital Building at Lh.Naifaru

15	Disabled toilet railing is not mentioned in the BOQ. Please provide the details.	Hand railings are required. Standard railing system is to be included. All railing shall be Cotto or equivalent railings.
----	--	---

